

Exemplar 96 Mustang airbag sensor (ball Cylinder type)

95 Mustang front airbag sensor with cut wire harness – airbag failed to deploy driver of vehicle was killed



## Cut wire harness of airbag sensor on 95 mustang



Cut wire harness (electrical connector was destroyed in crash) of 95



mustang

Volvo Tractor (for 18 wheeler) in which driver airbag failed to deploy



General Motors Airbag System Sensing Diagnostic Modules (typical of Cobalt) ignition switch vehicles





## Bosch Airbag Control Module to be downloaded off of Chrysler



## Example of Toyota Electronic Data (Crash) Recorder download information –

<b>b</b> 7 <b>b</b> -																										
PIDs	PID		ita																							
	00	BC	C 60	) DC	01																					
	01	00	3																							
	03	34	37	30	38	30	30	30	30	30	30	30	30	30	30	3.0	30	30	3.0	30	30	30	зο	3.0	3.0	
			30													20		20	~ ~			50	50	50	50	
	04		FF						50	30		50														
	05			1.1	r r																					
		01																								
	06	16																								
	0A	01																								
	0B	00	)																							
	20	80	00	00	01																					
	21	0.0	31																							
	40		00		01																					
	60		00																							
	80		00																							
	AO		00																							
	CO	00	00	0.0	01																					
	EO	CO	10	00	00																					
	El	17	17																							
	E2	00	5B	19	11	00																				
	00	00				2.2																				
		20																								
EEPROM	Nddroop	De	÷-																							
EEFROM	Address	Da	ca																							
	_																									
	0		00																							
	10	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00									
	20	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00									
	30	00	00	00	00	7F	FD	00	00	AS	03	00	16	00	00	00	00									
	40	00	00	00	0.0	0.0	00	0.0	00	00	0.0	0.0	00	00	00	0.0	00									
	50		00																							
	60	00	20		24	01	01	1.4	55	00	14	22	00	24	24	00	20		-							
		00	26	012	21	07	00	00	33	00	00	00	00	00	00	υŲ	00									
	70		00																							
	80	64	14	22	64	14	22	64	19	60	1E	5C	1E	04	00	00	55									
	90	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00									
	AO	00	55	00	00	04	00	02	1D	11	19	2A	31	32	35	1F	0¢									
	B0	04	FE	00	00	01	00	00	02	<b>04</b>	DB	00	55	00	05	15	14									
	CO	1C	1C	22	55	08	00	01	01	01	02	02	00	00	03	02	00									
	DO	00	$\mathbf{FF}$	01	01	00	FF	00	00	0.0	36	0.0	55	00	03	14	01									
	EO		FΕ																							
	FO		FF																							
	100	01	PP	1312	01	07	02	0.3	05	22	0.0	03	00	FD	L.P.	00	01									
			FF																							
	110		05																							
	120	03	F4	00	15	2B	lA	23	ЗC	14	ΟE	F9	FΕ	FA	DD	00	00									
	130	00	00	30	55	00	06	05	3 O	$\mathbf{FE}$	FE	40	55	00	ΰO	00	00									
	140	00	01	00	$\mathbf{FF}$	$\mathbf{FE}$	00	Οl	01	00	FF	00	01	00	FF	FF	00									
	150		00																							
	160		00																							
	170		08																							
	180																									
		22	03	F E	00	00	00	00	00	T0	35	00	04	04	6A	P.E	FE									
	190	40	55	00	00	00	00	00	00	00	00	00	00	00	00	00	00									
	1A0		00																							
	180		00																							
	100	00	00	00	00	00	0 Q	00	00	00	00	00	00	00	00	00	00									
	1D0	00	00	00	00	00	00	00	00	00	00	00	on	00	00	00	00									
	1E0	00	00	00	00	00	00	00	00	00	00	00	00	0n	00	no	00									
	1F0	00	00	00	00	00	00	0.0	00	00	00	00	00	00	0.0	00	00									
	TLO	00	υu	20	00	00	00	00	00	00	00	υŲ	00	00	00	00	00									

Inflated Side Rollover Curtain in GM Van (rear seat fatality)





Deployed Driver Airbag showing contact with Driver Occupant